

DEEP FRYER 2 x 8ℓ SPAZA



MANUFACTURING
SINCE 1966

Model: FFA1002



FEATURES

- A powerful floor standing unit that is reliable and cost effective
- This fryer has 2 x 8ℓ tanks
- Each insert has a powerful 3.4kW element
- There is an integrated splash back with basket hanger facility
- Ideal for smaller catering organizations
- Valve fitted to drain the oil easily
- Pilot light indicates when elements are energised
- Should the control thermostat fail, the safety switch will prevent the oil from overheating and flashing
- Operating temperature: 50°C - 190°C
- Working area constructed from Stainless Steel




NOTE:

- Stainless steel baskets sold separately
- Supplied flat packed
- Should Be Connected to 2 Separate 16amp Plugs on Separate Curcuits



ALL ANVIL EQUIPMENT COMES WITH A TWO YEAR WARRANTY ON COMPONENTS AND DEFECTIVE WORKMANSHIP.

www.anvilworld.com

Model: FFA1002

SPECIFICATIONS

POWER	2 x 3.4kW
VOLTAGE	230V - 50Hz
PACKAGING (W x D x H)	850 x 640 x 500 (mm)
UNIT (W x D x H)	813 x 628 x 1152 (mm)
NET WEIGHT	31.54kg
GROSS WEIGHT	33.2kg
SHIPPING VOLUME	0.27m ³
VOLUME OF OIL	2 x 8ℓ
PRODUCT OUTPUT	Approx 10kg French Fries Per Hour

OPTIONAL EXTRAS
BASKET

CODE	DESCRIPTION
FFB2250	Fryer Basket - S/Steel

NOTE

- When viewing the appliance from the front in it's usual operating position, the width (W) of the product is the total distance from left to right; the depth (D) of the product is the total distance from the front to the back; the height (H) is the total distance from the bottom of the product to the top. Pictures may vary from actual product.

DISCLAIMER

- Output performance figures quoted are dependent on various factors. Anvil reserves the right, without notice, to make changes and revisions to product specifications, materials and design, when we believe it will provide better performance, durability, and efficiency. Unit measurements may vary depending on point of reference.



ALL ANVIL EQUIPMENT COMES WITH A TWO YEAR WARRANTY ON COMPONENTS AND DEFECTIVE WORKMANSHIP.

www.anvilworld.com